

SUPPLIMENTARY AGENDA FOR 53RD OCC MEETING TO BE HELD
ON 27.08.16

SA-1:- DELAYED REPORTING OF OCCURRENCE AT 220 KV S/s SIDHI:- On 25.08.2016 at 12:20 Hrs. Circuit Breaker trip coil of 132 KV Sidhi – Mauganj Ckt failed/burnt at 220 KV S/s sidhi resulting in 132 KV Bus fault and tripping of all connected 132 KV feeders and transformers at 220 KV S/s Sidhi. Consequently 132 KV supply failed at 220 KV S/s Sidhi, 132 KV S/s Sidhi, 132 KV S/s Deosar & 132 KV S/s Mauganj. It has been gathered that the incident was reported after Half an Hour. Moreover some more time has been taken for providing the relay indication. Due to above the elements could be restored from 13:01 Hrs. due to which 40-50 min interruption took place at effected place.

In view of the above MPPTCL is requested to ensure that the intimation of incident and details of tripping/indication is provided immediately to SLDC during any occurrence in real time to avoid delay in restoration of important grid element and also ensure that such incidences are not repeated in future for safe & reliable grid operation.

[Action : MPPTCL]

SA-2:- FREQUENT TRIPPING OF 132 KV VSTPS – W Aidhan Ckt:- It has been observed that 132 KV VSTPS – Waidhan Ckt is being tripped on transient fault frequently. On following dates the Ckt tripped as under:-

1. 19.08.2016 at 08:58 hrs.
2. 21.08.2016 at 16:23 Hrs.
3. 25.08.2016 at 11:27 Hrs.

In the above matter WRLDC has also informed that NTPC has intimated that such frequent trippings of circuit emanating from VSTPS is causing voltage dip at NTPC station.

In view of the above MPPTCL is requested for carrying out relay testing/line maintenance and to ensure the healthiness of line to avoid such frequent trippings in future.

[Action : MPPTCL]